

## Visual Edge Checklist



Sealed Prototype Robot Kit  
(See Pages 3-5 for details)



Microcontroller



TX-RX Kit



Small PMW Bundle



7.2V Battery



Power Cord



Smart Charger



Battery Strap



9.6v Transmitter Battery



Safety Glasses




Intake roller(x2)



Shaft 12" (x2)



Spacer pack



Gusset pack




Plate (x2)



Hinge (x2)



Drive shaft lock (x4)



Standoff .50" (x10)




Standoff 1.00" (x10)




1/2" (28) 3/4" (14) screw



65 NUTS!



Segmented Angle (4 pack)



Bar (8)



Tool kit

Prototype Robot Kit



2 wire motor(4)



Shaft collars(21)



2"shaft(4)  
3"shaft(6)  
4"shaft(1)



Bearing Flat(20)



12 tooth gear(4)  
36 tooth gear(4)  
60 tooth gear(6)  
84 tooth gear(2)




5" wheel(4)



4" wheel(4)



2.5" wheel(4)



25 hole bar(2)







Plate 5x15 hole(1)



Chassis Bumper 15hole (2)



Chassis Rail 16hole(4)



C-Channel, 1x2x1x15hole(2)  
C-Channel, 1x2x1x25hole(1)



Motor Controller(4)



Robot AA Battery Holder(1)




12”PWM Extension(1)



8-32 1/2” Screw(54)  
8-32 3/8” screw(15)  
8-32 1/4”Screw(12)  
8-32 1/8”Screw(2)  
6-32 1/4”Screw(10)  
6-32 1/8”Screw(8)



8-32 Nuts(34)



3”(4), 2”(4), 1”(6), 1/2”(4) 8-32 Standoff



Shaft Spacer: Thick(2), Thin(12)



4" Tie Wraps(100)



Bearing Pop Rivet(50)



Allen Wrench 5/64"(1)  
Allen Wrench 3/32"(1)  
Open Ended Wrench(1)  
Nut Starter(1)  
Manual(1)